




in servo flange casing 20
wiper rotatable without limit stops
output +20 mA...4 mA...+20 mA
V-characteristic curve
burden max 600 Ω
supply 20-30VDC
2-wire system
torque ≤ 10 cnp and $\leq 0,1$ Nm



marking of sense of rotation



Operating instructions for rotary transducer PW ; PK ; FW 620 - MU / 1 - 02


1. Fixing and centering according to ill.1
- 1.1. Bring the drive mechanism in starting position and connect the angle signal converter.
2. For possibilities of wiring and measuring ranges, look at ill.2.
3. Adjust the angle signal converter mechanically and fix it at 0 mA resp. 4 mA (ill.2).
4. Take end position of drive mechanism. Effect fixing of the range via a switch (ill.4) according to the angle of rotation and the model.
5. Adjust the slope trimmer (ill.4) at 20 mA.
6. Check the starting position if necessary, check the zero trimmer at 0 mA resp. 4 mA.
7. Sense of rotation can be modified after taking off the cover of the angle signal converter (ill.3).

Attention

Please do not overtwist zero point and steepness of potentiometer.


ill.1

Fastening




ill.2


2 wire system



3 wire system




4 wire system





ill.3

Designation of sense of rotation

turning
sense right



turning
sense left



ill.4

switch	2 wire system 0...20 mA	3/4 wire system 0...20 mA	3/4 wire system 4...20 mA
0	196 ... 356	248 ... 355	
1	106 ... 195	135 ... 248	
2	64 ... 106	88 ... 135	71 ... 110
3	53 ... 88	64 ... 106	53 ... 86
5			110 ... 195
6			195 ... 355

Ersatz für BA 109/86.003 E

Bedienungsanleitung für Drehwinkelmeßumformer PW ; PK ; FW 620 - MU / i - 02

1. Befestigung und Zentrierung nach Abb.1
- 1.1. Antriebsmechanik auf Anfangsstellung bringen und Drehwinkelmeßwertumformer ankuppeln.
2. Beschaltungsmöglichkeiten und Meßbereiche siehe Abb.2.
3. Drehwinkelmeßwertumformer mech. justieren und auf 0 mA bzw. 4 mA einstellen (Abb.2).
4. Endstellung der Antriebsmechanik anfahren. Bereichseinstellung mittels Schalter (Abb.4) gemäß Drehwinkel und Ausführungsart vornehmen.
5. Steilheitstrimmer (Abb.4) auf 20 mA justieren.
6. Anfangsstellung kontrollieren. Bei Bedarf Nullpunkttrimmer (Abb.4) auf 0 mA bzw. 4 mA überprüfen.
7. Drehsinn kann nach Abnahme der Kappe am Drehwinkelmeßwertumformer geändert werden (Abb.3).

Abb.1

Befestigung






Abb. 2

2-Leitertechnik



3-Leitertechnik



4-Leitertechnik






Abb.3

Drehsinnkennzeichnung

Drehsinn rechts



Drehsinn links



Achtung

Potentiometer Nullpunkt und Steilheit nicht mit Gewalt überdrehen.







Abb. 4

Schalter	2-Leitertechnik 0...20 mA	3/4-Leitertechnik 0...20 mA	3/4-Leitertechnik 0...20 mA
0	196 ... 356	248 ... 355	
1	106 ... 195	135 ... 248	
2	64 ... 106	88 ... 135	71 ... 110
3	53 ... 88	64 ... 106	53 ... 86
5			110 ... 195
C			195 ... 355

Ersatz für BA 109/B6.003

View without cover



type designation

PW 6 20 d / MU - 10 1

