


100JB

New Product


Low-cost and high performance, seesaw type potentiometer for Z axis mounted

Nomenclature




Number of potentiometers to be mounted. ●
 3...3 potentiometers mounted.
Number of switches to be mounted. ●
 0...no switch mounted.
With spring return device : ●
 R3 : with spring return device for 3-dimensional coordinate type.
Mounting accessories : G : with dust proof rubber cover. ●

Standard Dimensions



Panel Arrangements



Note : 4 pcs. of mounting screws (M3 × 8) are attached.

(Unit : mm)

