	GESSMANN Industrial Controllers	Single axis controller S 22 Spare parts				/204 2002	
	The spindle block Pos. 1 incorporates an internal bellow and ring nut. By all spare part orders it is nessesary to inform us switch gear.						
		Spindle block with schematic representation of the master controller installation and deflection directions. Version shown for left hand side installation (right-hand side installation is mirror image).	3 ← → 4 left Deflect to DIN	1 2 ion directio 15025	₹ right ns designa	5 6 ted	
Pos.	S 22		Drawing No.	Туре	Weight gramm	Price EURO	
1 2 3 4 5			KHS/400	S 22	600		
10 11 12 13 14	Spring return in 0-position Friction brake Control-handle with knob solid with joint Control-handle with latch for mechanical zero interlock with joint Control-handle with dead man's button (mechanical parts) with joint Control-handle with signal button (mechanical parts) with joint Control-handle with push button (mechanical parts) with joint Control-handle with flat push button (mechanical parts) with joint Control-handle with flat push button (mechanical parts) with joint Control-handle with flat push button (mechanical parts) with joint Control-handle with palm grip B 5 with joint Control-handle with palm grip B 5 with push button top (mechanical parts) with joint Control-handle long or short 140, 100 mm More knobs, grips and T-grips with and without signal devices look catalog 1/228		KMFD/58 KHS/167	Z R	20 20		
20 21 22 23 24 25 26 27 28 29			KHS/118 KHS/122 KHS/119 KHS/120 KHS/177 KHS/646 KBAD/254 KBAD/311	M T D DV B 5	50 50 50 60 60 40 60		
41 42 43	Prepared for mounting potentiometer shaft 6 mm adjusting angle 2 x 150° Prepared for mounting potentiometer e.t.c. adjusting angle variable More potentiometer e.t.c. look catalog 1/240		KHS/400	(P) (P)			
80 81 82 83 84 85 86 87 88 89 90 91	Bellows Ring nut (for mounting the bellow) Gasket (for spindle block Pos. 1) Gasket cap (for push button Pos. 24) Knob solid (for Pos. 20) Knob-type with shaft activities (for Pos. 21-25, 1 Pos. only) Spare gear with cam shaft (for Pos. 20-27) Notching (1 notching lever/notching disk with roll, 1 notching spring) Microswitch (166) 2 A 250 V AC 15 with roll-lever and insulating disk (for master switch) Microswitch (166) 2 A 250 V AC 15 with roll-lever, 2 insulating disk and contact striker (for Pos. 22, 23, 24, 27)		KMD 20 KMS 463 KMD 33 KBAD 66 KHS/400				